

Douglas County, KS Public Works: All Recorded Section Corner Reference Ties

Northing: 219964.016	Easting: 2075835.996	Elevation: 864.49	Coordinate Source: DGCO Static
--------------------------------	--------------------------------	-----------------------------	--

N09P	Corner: 1/4 WL	Section: 21	Township: 13	Range: 19	Surveyor: Stephan C. Tufte Date Surveyed: 9/13/2019
Corner Status Prior to Survey: Existent					
Monument Condition: Found					
All Measurements Are: Horizontal					
Original Description:					
Monument Description: 2" aluminum cap in monument box					
Reference Tie 1:	40d spike and bottlecap in northwest face of power pole, 110.72' NE			Reference Tie 5:	in existing centerline of north-south asphalt roadway
Reference Tie 2:	mag nail and washer in south face of power pole, 43.95' E			Reference Tie 6:	existing centerline of asphalt roadway running west, 109' S
Reference Tie 3:	top center south end of 18" corrugated metal pipe, 47.59' SE			Reference Tie 7:	.
Reference Tie 4:	Corps of Engineers disk "RM-8" in concrete, 42.98' W			Reference Tie 8:	.

N09P	Corner: 1/4 WL	Section: 21	Township: 13	Range: 19	Surveyor: Timothy R. Sloan Date Surveyed: 10/29/2018
Corner Status Prior to Survey: NOEC					
Monument Condition: Found					
All Measurements Are: Horizontal					
Original Description:					
Monument Description: 2" aluminum cap in monument box					
Reference Tie 1:	spike and washer in power pole, 44.0' E			Reference Tie 5:	on centerline of travelway of north-south road
Reference Tie 2:	top south end of entrance pipe, 47.4' SE			Reference Tie 6:	.
Reference Tie 3:	concrete Corps of Enginner monument, 43.0' W			Reference Tie 7:	.
Reference Tie 4:	centerline of travelway of road to west, 109' S			Reference Tie 8:	.

N09P

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: Timothy R. Sloan
Date Surveyed: 5/30/2017

Corner Status Prior to Survey: Endangered**Monument Condition:** Found**All Measurements Are:** Horizontal**Original Description:****Monument Description:** 2" Aluminum cap

Reference Tie 1:	Monument Coordinates: N=219963.990, E=2075835.993
Reference Tie 2:	Douglas County Survey Marker N=217627.644, E=2075989.789
Reference Tie 3:	Douglas County Survey Marker N=222680.873, E=2075700.661
Reference Tie 4:	.

Reference Tie 5:	.
Reference Tie 6:	.
Reference Tie 7:	.
Reference Tie 8:	.

N09P

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: Brad Zilliox
Date Surveyed: 11/3/2015

Corner Status Prior to Survey: Existent**Monument Condition:** Found**All Measurements Are:** Horizontal**Original Description:****Monument Description:** 2" aluminum cap, illegible, 0.30' below top of asphalt

Reference Tie 1:	36.10' E to PK nail set in south face power pole
Reference Tie 2:	61.70' W to PK nail set in south face of power pole
Reference Tie 3:	109.50' S to centerline of intersection of N 1150 Rd and E 1000 Rd
Reference Tie 4:	near centerline of E 1000 Rd

Reference Tie 5:	.
Reference Tie 6:	.
Reference Tie 7:	.
Reference Tie 8:	.

N09P

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: Ron Shanks
Date Surveyed: 10/14/2015

Corner Status Prior to Survey: Existent**Monument Condition:** Found**All Measurements Are:** Horizontal**Original Description:****Monument Description:** 2" aluminum cap**Reference Tie 1:** mag nail in south face power pole 61.73' W**Reference Tie 2:** mag nail in south face power pole 36.18' E**Reference Tie 3:** mag nail in northwest face power pole 107.45' NNE**Reference Tie 4:** mag nail in northeast face power 116.62' NNW**Reference Tie 5:** traveled way driveway of house #1148 17' S**Reference Tie 6:** traveled way E1000 Rd 0.7' E**Reference Tie 7:** 0.2' below road surface**Reference Tie 8:****N09P**

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: Steven Williams
Date Surveyed: 9/1/2005

Corner Status Prior to Survey: Existent**Monument Condition:** Found**All Measurements Are:** Horizontal**Original Description:****Monument Description:** 2" ALUMINUM CAP IN ASPHALT 0.3' BELOW GRADE**Reference Tie 1:** PK NAIL AND WASHER IN SOUTH FACE POWER POLE 36.2' E**Reference Tie 2:** PK NAIL AND WASHER IN SOUTH FACE POWER POLE 61.9' W**Reference Tie 3:** SOUTH END 15" CMP 64.6' NE**Reference Tie 4:** NE CORNER CONCRETE BASE FOR "CLINTON LANE" SIGN 191.2' SSW**Reference Tie 5:****Reference Tie 6:****Reference Tie 7:****Reference Tie 8:**

N09P

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: DGCO
Date Surveyed: 5/11/2005

Corner Status Prior to Survey: Existent**Monument Condition:** Found**All Measurements Are:****Original Description:****Monument Description:** Corps Mon

Reference Tie 1:	PK & SHINER IN PP S FC 61.90' W
Reference Tie 2:	CONC BASE BROKEN CORPS MARKER 29.83' W
Reference Tie 3:	PK & SHINER IN PP S FC 36.28' E
Reference Tie 4:	0.60' EAST OF CL N-S ROAD

Reference Tie 5:	
Reference Tie 6:	
Reference Tie 7:	
Reference Tie 8:	

N09P

Corner: 1/4 WL
Section: 21
Township: 13
Range: 19

Surveyor: Corps
Date Surveyed: 5/14/1976

Corner Status Prior to Survey:**Monument Condition:****All Measurements Are:****Original Description:** Limestone 3x12x18**Monument Description:** Stone

Reference Tie 1:	spk & wshr in PP 34.45' E
Reference Tie 2:	spk & wshr in 60" tree 52.47' NW
Reference Tie 3:	spk & BC in PP 84.70' SW
Reference Tie 4:	

Reference Tie 5:	
Reference Tie 6:	
Reference Tie 7:	
Reference Tie 8:	

N09P**Corner:**

1/4 WL

Section:

21

Township:

13

Range:

19

Surveyor:**Date Surveyed:** 4/26/1955**Corner Status Prior to Survey:****Monument Condition:****All Measurements Are:****Original Description:** Limestone 3x12x18**Monument Description:**

Reference Tie 1: spk & wshr in PP S fc 61.95' WNW

Reference Tie 5:

Reference Tie 2: KPL spk head in PP 84.22' SW

Reference Tie 6:

Reference Tie 3: 2 1/2x4x24 conc mk witness stone 35' E

Reference Tie 7:

Reference Tie 4: brown book 38 p 8

Reference Tie 8:

N09P**Corner:**

1/4 WL

Section:

21

Township:

13

Range:

19

Surveyor:**Date Surveyed:** 1/1/1927**Corner Status Prior to Survey:****Monument Condition:****All Measurements Are:****Original Description:** Limestone 3x12x18**Monument Description:** Limestone - flush with surface

Reference Tie 1: in line with hedge running E

Reference Tie 5:

Reference Tie 2: center of walnut tree 33.0' W

Reference Tie 6:

Reference Tie 3: TP 27.8' NE

Reference Tie 7:

Reference Tie 4: HP 33.70' E

Reference Tie 8:

N09P**Corner:**

1/4 WL

Section:

21

Township:

13

Range:

19

Surveyor:**Date Surveyed:****Corner Status Prior to Survey:****Monument Condition:****All Measurements Are:****Original Description:** Limestone 3x12x18**Monument Description:** Big Limestone - mk - 6X8X? - 12" deep

Reference Tie 1: CL of walnut tree 33.3' W

Reference Tie 5:

Reference Tie 2: in line with hedge W

Reference Tie 6:

Reference Tie 3: spk in TP 30.7' E

Reference Tie 7:

Reference Tie 4: spk & wshr in PP 61.95' W

Reference Tie 8:

N09P**Corner:**

1/4 WL

Section:

21

Township:

13

Range:

19

Surveyor:**Date Surveyed:****Corner Status Prior to Survey:****Monument Condition:****All Measurements Are:****Original Description:** Limestone 3x12x18**Monument Description:** StoneReference Tie 1: 2 1/2x4x24 conc mk 35' E 90 degrees to
Section li

Reference Tie 5:

Reference Tie 2:

Reference Tie 6:

Reference Tie 3:

Reference Tie 7:

Reference Tie 4:

Reference Tie 8: